
ACCESSORIES


01 / Components and basic assembly




1. Select the L or C profile and its matching left/right end caps.
2. Insert the end caps; use the corner mounting bracket where required.
3. Check alignment and fit before final fastening.

ACCESSORIES

03 / Cabinet placement and drilling references




Drilling Diagram with Mounting Bracket



Detail 'X'
Fig. 3

Drilling Diagram with Mounting Bracket



Detail 'Y'

Cabinet cut length shown: X - 2 mm.

Refer to Detail X and Detail Y for their respective drilling positions.

All numeric drawing dimensions are in millimetres.